From: Debra M. Beckwith

To: Debra M. Beckwith

Subject: Bridge Advertisement (DSI 22-010) Structural Steel coatings

Date: Monday, January 30, 2023 10:59:40 AM

The EPG, Bridge Standard Drawings, MicroStation cells, and Standard Specifications have been updated as described below:

Implementation Statement: Effective immediately for all plans not yet submitted to Design.

(The Implementation Statement is a recommendation by the Development Section. The SPM is responsible for the level of implementation for any particular job.)

| | Description of Change |
|---|--|
| EPG: 751.1.2.9; 751.6; 751.14.5.8; 751.50, 1045 Bridge Standard Drawings: REDECK01; RHB07 MicroStation Cells: (New) PaintOverlapE Std. Specifications: 1045, 1080, 1081 Standard Plans: NA Bridge Special Provisions: NA | These revisions contain significant changes to structural steel coating policy. System G has replaced System H as the preferred coating for weathering steel bridges. System G has replaced calcium sulfonate as the preferred overcoating system. Calcium sulfonate has been removed from the EPG and specifications as a viable overcoating product. System I is considered a viable option for coating weathering steel. System I finish coating shall be an epoxy-based polysiloxane per the specifications. The epoxy-based products appear to work better than acrylic-based for MoDOT projects. Organic Zinc Primer has been added to the specifications and is considered a viable option for recoating when System G, H or I is required. Inorganic zinc is still the preferred primer for shop fabrication. Language has been added to address concerns with overcoating vinyl coatings. Epoxy-mastics are recognized as an alternative short-term solution for overcoating lead-based coatings. Standard drawing RHBO7 (paint overlap) has been voided and replaced by a standard cell (PaintOverlapE) since only one figure is needed after removing the paint overlap for new-on-new coatings. Standard drawing REDECK01 has been updated to reflect revised wording of standard notes. |
| | 751.1.2.9; 751.6; 751.14.5.8; 751.50, 1045 Bridge Standard Drawings: REDECK01; RHB07 MicroStation Cells: (New) PaintOverlapE Std. Specifications: 1045, 1080, 1081 Standard Plans: NA Bridge Special Provisions: |

to view more details about this (or any) revision,

use the <u>Revision Index Database</u>, located under Completed Revisions on Development's Sharepoint page.

Instructions:

Under Tables (left-hand side) double-click on RevisionRecords.

Click on the link under the Effective Date to access documentation for the completed revision.

Debra M. (Debbie) Beckwith

Structural Specialist – Development Section

Missouri Department of Transportation

Central Office – Bridge Division 105 W. Capitol Ave., P.O. Box 270, Jefferson City, MO 65102 573-522-8718 www.modot.org